





AZTEEG X1 3DP 3D PRINTER CONTROLLER WIRING DIAGRAM

STEPPER MOTORS



AZTEEG X1 3DP 3D PRINTER CONTROLLER WIRING DIAGRAM

USING A SEPARATE POWER SUPPLY
FOR STEPPER MOTORS



AZTEEG X1 3DP CONTROLLER
WWW.PANUCATT.COM

reprap.org/wiki/Azteeg_X1

