




AZTEEG X5 MINI V3.0 4-AXIS MOTION CONTROLLER WIRING DIAGRAM


STEPPER MOTORS



X[ALPHA] AXIS Y[BETA] AXIS Z[GAMMA] AXIS EXTRUDER





VREF pin for digipot current control
Available on SD8825, SD5984 and SD6128



POWER INPUT
PC POWER SUPPLY OR AC/DC SWITCHING PS 12-30VDC

Mini Blade Fuse 20A - 30A



+Vin = +Main power supply
SW[-] = Switched ground

LOW POWER FANS ONLY

END STOPS
Location of C and NO on switch may vary. Check markings.